

REPORT NUMBER: 201U-VER-04-06

**SAFETY COMPLIANCE TESTING FOR FMVSS 201
OCCUPANT PROTECTION IN INTERIOR IMPACT
UPPER INTERIOR HEAD IMPACT PROTECTION**

**HYUNDAI MOTOR COMPANY
2004 HYUNDAI XG350 4-DOOR SEDAN**

NHTSA NUMBER: C40500

GD TEST NUMBER: 8730-06

**ADVANCED INFORMATION ENGINEERING SERVICES
A GENERAL DYNAMICS COMPANY
TRANSPORTATION SCIENCES CENTER
P.O. BOX 400
BUFFALO, NEW YORK 14225**



Test Date: February 6, 2004

FINAL REPORT

PREPARED FOR:

**U. S. DEPARTMENT OF TRANSPORTATION
National Highway Traffic Safety Administration
Enforcement
Office of Vehicle Safety Compliance
Mail Code: NVS-220, Room 6111
400 Seventh Street, SW
Washington, DC 20590**

This publication is distributed by the U. S. Department of Transportation, National Highway Traffic Safety Administration, in the interest of information exchange. The opinions, findings and conclusions expressed in this publication are those of the author(s) and not necessarily those of the Department of Transportation or the National Highway Traffic Safety Administration. The United States Government assumes no liability for its contents or use thereof. If trade or manufacturers' names or products are mentioned, it is only because they are considered essential to the object of the publication and should not be construed as an endorsement. The United States Government does not endorse products or manufacturers.

Prepared by:

James Czarnacki
James Czarnacki, Project Engineer

Approved by:

David J. Gravale
David J. Gravale, Program Manager
Transportation Science Center

Approval Date:

March 9, 2004

FINAL REPORT ACCEPTANCE BY:

He Nuss
NHTSA, Office of Vehicle Safety Compliance

3.23.2004
Date of Report Acceptance

TECHNICAL REPORT STANDARD TITLE PAGE

1. Report No. 201U-VER-04-06		2. Government Accession No.		3. Recipient's Catalog No.	
4. Title and Subtitle Final Report of FMVSS 201 Compliance Testing of a 2004 Hyundai XG350, 4-Door Sedan, NHTSA No. C40500		5. Report Date / Final Test Date February 6, 2004			
		6. Performing Organization Code VER			
7. Author(s) David J. Travale, Program Manager James Czarniecki, Project Engineer		8. Performing Organization Report No. 8730-06			
9. Performing Organization Name and Address Advanced Information Engineering Services A General Dynamics Company 4455 Genesee Street Buffalo, New York 14225		10. Work Unit No.			
		11. Contract or Grant No. DTNH22-99-C-01005			
12. Sponsoring Agency Name and Address U.S. Department of Transportation National Highway Traffic Safety Administration Office of Vehicle Safety Compliance Mail Code: NVS-220 400 Seventh, SW, Room 6111 Washington, D.C. 20590		13. Type of Report and Period Covered Final Report February 2004			
		14. Sponsoring Agency Code NVS-220			
15. Supplementary Notes					
16. Abstract Compliance tests were conducted on the subject vehicle, a 2004 Hyundai XG350, 4-Door Sedan, in accordance with the specifications of the Office of Vehicle Safety Compliance Test Procedure TP-201U-01 for determination of FMVSS 201 compliance. Test failures identified were as follows in the table below:					
Target Point	Horizontal	Vertical	Velocity	HIC	HICd
None	-	-	-	-	-
None	-	-	-	-	-
17. Key Words Compliance Testing Safety Engineering FMVSS 201			18. Distribution Statement Copies of this report are available from: NHTSA Technical Reference Division National Highway Traffic Safety Admin. 400 Seventh St., SW, Room 5108 Washington, DC 20590 Telephone No.: 202-366-4946		
19. Security Classif. (of this report) UNCLASSIFIED		20. Security Classif. (of this page) UNCLASSIFIED		21. No. of Pages	22. Price

Form DOT F1700.7 (8-69)

TABLE OF CONTENTS

SECTION		PAGE
1	PURPOSE AND TEST PROCEDURE	1-1
2	SUMMARY OF UPPER INTERIOR HEAD IMPACTS	2-1
3	SUMMARY OF TEST RESULTS AND DATA PLOTS	3-1
APPENDIX A	PHOTOGRAPHS	A-1
APPENDIX B	PART 572L PERFORMANCE CALIBRATION IN SUPPORT OF VEHICLE SAFETY COMPLIANCE TESTING FOR OCCUPANT PROTECTION IN INTERIOR IMPACT	B-1

LIST OF DATA SHEETS

DATA SHEET	DESCRIPTION	PAGE NO.
2-1	SUMMARY OF UPPER INTERIOR HEAD IMPACT TESTS	2-2
2-2	GENERAL TEST AND VEHICLE PARAMETER DATA	2-3
2-3	TARGET MEASUREMENT REFERENCE SHEET	2-5
2-4	APPROACH ANGLE LIMITS	2-6
2-5	TARGET IMPACT LOCATION ON FMH SUMMARY	2-7

SECTION 1

PURPOSE AND TEST PROCEDURE

This head impact compliance test is part of the FMVSS 201 Upper Interior Head Impact Protection Test Program sponsored by the National Highway Traffic Safety Administration (NHTSA) under Contract No. DTNH22-99-C-01005. The purpose of this head impact compliance test was to determine whether the subject vehicle, 2004 Hyundai XG350 4-Door Sedan, NHTSA No. C40500, meets the performance requirements of FMVSS 201, Occupant Protection in Interior Impact. The compliance test was conducted in accordance with the OVSC Laboratory Test Procedure No. TP-201U-01 dated April 03, 1998.

SECTION 2

SUMMARY OF UPPER INTERIOR HEAD IMPACTS

A 2004 Hyundai XG350, 4-Door Sedan, NHTSA No. C40500, was impacted at various locations throughout its upper interior by a 4.54 kg 50th percentile headform. A total of ten (10) impacts were performed in this test series. The target area impacts were chosen by the NHTSA Contracting Officer's Technical Representative (COTR). A summary of test results can be found on data sheet 2-1. The ten (10) area chosen for testing were:

BP4	SR3	RP2	BF1	AP3
AP1	BP2	URBP	URRP	AP2

The selected impact areas on the test vehicle appeared to comply with the performance requirements of FMVSS 201.

Five Free Motion Headforms (FMH), were used in this test series. All five FMH's were calibrated prior to and after the test series. Calibration information are included in Appendix B. Each FMH weighed 4.54 ± 0.5 kg and has an orthogonal tri-axis accelerometer pack mounted at the center of gravity (c.g.).

A total of three (3) channels of data for each target impact test are recorded on a Keyser Thredle data acquisition system. Data plots, along with still photographs, can be found in Section 3 of this report.

To document each target area impact test, one Weinberger high-speed video camera was placed at various locations to view the headform contact with the selected target area.

DATA SHEET 2-1

SUMMARY OF UPPER INTERIOR HEAD IMPACT TESTS

VEHICLE YEAR/MAKE/MODEL/STYLE:	2004 Hyundai XG350 4-Door Sedan
VIN:	KMHFU45E04A273719
DATE OF MANUFACTURE:	March 6, 2003(SHE CERTIFICATION LABEL)
COLOR:	Red (Bordeaux)

TARGET CODE	Target Coordinates						Approach Angles (degrees)		Velocity (gph)	FMH HIC	HIC(d)
	Driver Side			Passenger Side							
	X(mm)	Y(mm)	Z(mm)	X(mm)	Y(mm)	Z(mm)	Horizontal	Vertical			
AP1	1197.6	-561.4	918.6	1199.7	551.9	919.7	122	42	23.74	953.5	885.8
AP2	1058.9	-609.8	831.9	1057.9	604.7	833.2	218	43	23.59	496.2	540.8
AP3	948.3	-632.9	763.7	950.2	626.7	766.6	134	45	23.35	512.6	553.1
BP1	1687.9	-486.5	1005.7	1690.9	480.1	1006.3	90	22	23.51	812.0	779.1
BP2	1660.9	-598.7	764.8	1663.9	598.2	764.9	270	7	23.59	854.2	810.9
BP3	1642.2	-623.8	806.2	1644.0	620.9	803.7	Relocated 1 circle		-	-	-
Rel. BP3	1635.8	-627.1	819.7	1640.7	618.6	821.9	-	-	-	-	-
BP4	1702.1	-662.0	701.4	1707.0	662.7	705.0	135	-10	23.5	667.7	670.2
FH1	1133.8	-457.2	960.6	1138.9	450.5	961.6	-	-	-	-	-
FH2	1114.4	-304.7	969.1	1120.2	300.4	967.7	-	-	-	-	-
RP1	2490.8	-520.1	955.7	2493.3	517.0	957.3	Relocated 2 circle		-	-	-
Rel. RP1	2527.1	-535.5	936.2	2520.2	526.7	938.7	-	-	-	-	-
RP2	2449.7	-614.4	802.3	2460.2	615.1	806.2	79	14	23.68	546.0	578.3
RH	2486.2	-348.0	1009.7	2489.4	343.1	1009.2	-	-	-	-	-
SR1	1346.1	-507.6	958.8	1347.6	497.8	962.0	-	-	-	-	-
SR2A	1495.3	-514.2	987.5	1502.1	501.5	991.7	Relocated 2 circle		-	-	-
Rel. SR2A	1497.2	-493.5	964.5	1503.1	488.7	961.2	-	-	-	-	-
SR2B	1389.3	-516.1	981.5	1391.3	504.3	986.8	Relocated 2 circle		-	-	-
Rel. SR2B	1393.5	-497.7	955.9	1394.0	488.1	957.2	-	-	-	-	-
SR3	2003.1	-503.3	971.5	2009.8	489.6	981.8	90	41	23.47	424.3	486.5
URAP	1346.9	-421.3	1015.8	1349.7	403.9	1018.9	-	-	-	-	-
URBP	1587.7	-392.9	1053.2	1686.3	386.3	1052.5	270	47	23.42	848.6	806.7
URRP	2370.8	-424.5	1025.0	2370.9	420.6	1026.7	309	47	23.38	981.0	906.5

*HIC(d)=0.75446(Free Motion Headform HIC)+166.4

Hyundai's reference point for x,y,z coordinate correlation (Driver side front outboard seat belt hole x=1065 mm, y=-609 mm, and z=-38 mm) to General Dynamic's coordinate system.

DATA SHEET 2-2

GENERAL TEST AND VEHICLE PARAMETER DATA

TEST VEHICLE INFORMATION:											
Year/Make/Model/Body Style:				2004 Hyundai XG350 4-Door Sedan							
VIN:				KMHFU45E04A273719							
Month & Year of Manufacture:				March 6, 2003(SEE CERTIFICATION LABEL)							
Vehicle Body Color:				Red (Bordeaux)							
Engine Data:	6	Cylinders:	-	CID:	3.5	Liters:	-	cc			
Engine Placement:	x		Longitudinal;	or		-		Lateral			
Transmission:	5	Speed:	-	Manual:	x	Automatic:	--	Overdrive			
Final Drive:	-	Rear Wheel Drive;	x		Front Wheel Drive;	-	Four Wheel Drive				
Odometer Reading:	186		km								
Options:	x	A/C;	x	Power Steering;	x	Pwr.Brakes;	x	Pwr. Windows			
Interior Trim Information:											
1. Seat belt anchorages on both B-Pillars											
2. Front and rear outboard seating positions have grab handles on their side rails											

DATA FROM TIRE PLACARD:											
Tire Pressure (at capacity):				240		kPa FRONT					
				240		kPa REAR					
Recommended Tire Size:				P205/60R16							
Tires on Test Vehicle:				P205/60R16		Manufacturer:		Michelin			
Vehicle Capacity Data:											
Number of Occupants:		2	Front;	3	Rear;	-	3rd Seat:	5	Total		
Type of Front Seats:		x	Bucket;	-	Bench;	-	Split Bench				
Type of Front Seat Back:		-	Fixed;	x	Adjustable with	x	Lever or	-	Knob		
Vehicle Capacity Weight (VCW)=				390		kg (A)					
No. of Occupants x 68 kg. =				340		kg (B)					
Rated Cargo/Luggage Weight (RCLW) =				50		kg (A-B) Max RCLW = 136 kg.					

DATA SHEET 2-2

GENERAL TEST AND VEHICLE PARAMETER DATA (cont.)

TEST VEHICLE DELIVERED WEIGHT WITH MAXIMUM FLUIDS:					
Left Front	=	530	kg	Left Rear	= 322 kg
Right Front	=	530	kg	Right Rear	= 311 kg
TOTAL FRONT	=	1060	kg	TOTAL REAR	= 633 kg
% of Total Weight	=	62.6	%	% of Total Weight	= 37.4 %
TOTAL WEIGHT	=	1693	kg		

CALCULATION OF VEHICLE'S TARGET TEST WEIGHT:		
Total Test Vehicle Delivered Weight=	1693	kg (A)
+ Rated Cargo/Luggage Weight =	50	kg (B)
TEST VEHICLE TARGET WEIGHT =	1743	kg (A+B)

WEIGHT OF TEST VEHICLE (FULLY LOADED):					
Left Front	=	528	kg	Left Rear	= 346 kg
Right Front	=	528	kg	Right Rear	= 336 kg
TOTAL FRONT	=	1056	kg	TOTAL REAR	= 682 kg
% of Total Weight	=	60.8	%	% of Total Weight	= 39.2 %
TOTAL TEST WEIGHT	=	1738			
Weight of vehicle secured in test vehicles cargo area	=	50	kg		

TEST VEHICLE ATTITUDE (all dimensions in millimeters):					
AS DELIVERED:	Left Front	710	Left Rear	715	
	Right Front	710	Right Rear	708	
FULLY LOADED:	Left Front	710	Left Rear	701	
	Right Front	710	Right Rear	695	
Test Vehicle Wheelbase:		2750		millimeters	

TEST VEHICLE PITCH AND ROLL ANGLES:					
AS DELIVERED:	PITCH ANGLES		ROLL ANGLES		
	Left Door Sill	0.71	Front Bumper	0.21	
	Right Door Sill	0.41	Rear Bumper	0.21	
FULLY LOADED:	PITCH ANGLES		ROLL ANGLES		
	Left Door Sill	0.41	Front Bumper	0.21	
	Right Door Sill	0.11	Rear Bumper	0.21	
AS TESTED:	PITCH ANGLES		ROLL ANGLES		
	Left Door Sill	0.61	Front Bumper	0.21	
	Right Door Sill	0.41	Rear Bumper	0.21	

**DATA SHEET 2-3
TARGET MEASUREMENT REFERENCE SHEET**

VEHICLE YEAR/MAKE/MODEL/STYLE:	2004 Hyundai XG350 4-Door Sedan
VIN:	KMHFU45E04A273719
DATE OF MANUFACTURE:	March 6, 2003 (SEE CERTIFICATION LABEL)
COLOR:	Red (Bordeaux)

Measurements	Description	Left Side	Right Side
M	Seat fore / Aft travel (Front seats)	225	225
T°	Horizontal angle (CG-F1 (Left seat) to (Right A-pillar))	108	-
A1°	360° - T°	252	-
WE°	Horizontal angle (CG-F2 (Left seat) to (Left A-pillar))	204	-
A2°	A2° = W°	204	-
U°	Horizontal angle (CG-F2 (Left seat) to (Left B-pillar))	282	-
B1°	B1° = U°	282	-
V°	Horizontal angle (CG-FR (Left seat) to (Right B-pillar))	200	-
B2°	B2° = V°	200	-
W°	Horizontal angle (CG-F2 (Right seat) to (Right A-pillar))	-	156
A1°	A1° (Right) = W° (Right)	-	156
T°	Horizontal angle (CG-F1 (Right seat) to (Left A-pillar))	-	252
A2°	360° - T° (Right)	-	108
V°	Horizontal angle (CG-FR (Right seat) to (Right B-pillar))	-	160
B1°	B1° (Right) = V° (Right)	-	160
U°	Horizontal angle (CG-F2 (Right seat) to (Right B-pillar))	-	78
B2°	B2° (Right) = U° (Right)	-	78
J	A-pillar ((Plane 3) - (Plane 5))	310	310
J/2	J ÷ 2	155	155
D1	Upper Roof ((Plane A) - (Plane B))	1660	
D1/2	D1 ÷ 2	780	
D2	Upper Roof ((Plane C) - (Plane D))	1238	
D2/2	D2 ÷ 2	619	
.35D1	.35 x D1	546	
.35D2	.35 x D2	433.3	
N	B-pillar ((BPR) - (lowest point on the daylight opening forward of B-pillar))	400	400
N/2	B-pillar ((BP3) - (lowest point on the daylight opening forward of B-pillar))	200	200
N/4	B-pillar ((BP3) - (lowest point on the daylight opening forward of B-pillar))	100	100
Q	Other-pillar ((OPR) - (lowest point on the daylight opening forward of O-pillar))	-	-
Q/2	Other-pillar ((OP2) - (lowest point on the daylight opening forward of O-pillar))	-	-
D	((Corner of roof area, point 7) - (roof area center, point M))	700	700
3D/7	(3 x D) ÷ 7	300	300
MM	Widest door opening of slider door	-	-
M	MM ÷ 2	-	-

DATA SHEET 2-4

APPROACH ANGLE LIMITS


Left Side					Right Side				
Target Code	Horizontal Angles (deg.)		Vertical Angles (deg.)		Target Code	Horizontal Angles (deg.)		Vertical Angles (deg.)	
	Minimum	Maximum	Minimum	Maximum		Minimum	Maximum	Minimum	Maximum
AP1	204	252	-3	43	AP1	108	156	-3	43
AP2	204	252	-3	43	AP2	108	156	-3	43
AP3	204	252	-3	43	AP3	108	156	-3	43
BP1	200	282	-10	22	BP1	78	160	-10	22
BP2	ANY		0	7	BP2	ANY		0	7
BP3	200	282	-10	-9	BP3	78	160	-10	-9
BP4	200	282	-10	-10	BP4	78	160	-10	-10
CP1	-	-	-	-	CP1	-	-	-	-
CP2	-	-	-	-	CP2	-	-	-	-
RP1	270	345	-10	9	RP1	15	90	-10	9
RP2	270	345	-10	14	RP2	15	90	-10	14
FH1	180		0	50	FH1	180		0	50
FH2	180		0	50	FH2	180		0	50
RH	360		0	50	RH	0		0	50
SR1	270		0	40	SR1	90		0	40
SR2A	270		0	50	SR2A	90		0	50
SR2B	270		0	50	SR2B	90		0	50
SR3	270		0	41	SR3	90		0	41
URAP	ANY		0	50	URAP	ANY		0	50
URBP	ANY		0	47	URBP	ANY		0	47
URRP	ANY		0	47	URRP	ANY		0	47

Note: BP2 target location - Seat belt anchorage

DATA SHEET 2-5

SUMMARY TARGET IMPACT LOCATION ON FMH

VEHICLE YEAR/MAKE/MODEL/STYLE:	2004 Hyundai XG350 4-Door Sedan
VIN:	KMHFU45E04A273719
DATE OF MANUFACTURE:	March 6, 2003 (SEE CERTIFICATION LABEL)
COLOR:	Red (Bordeaux)



R RIGHT SIDE OF FACE


TARGET	Distance Above Point O (mm)	Distance Over From Pt. O (mm)
BP4	17	8 to the left
SR3	20	17 to the right
RP2	23	6 to the left
BP1	35	0
AP3	15	0
AP1	11	10 to the right
BP2	8	3 to the left
URBP	49	5 to the left
URRP	22	3 to the right
AP2	21	7 to the right

SECTION 3
SUMMARY OF TEST RESULTS AND DATA PLOTS

VEHICLE YEAR/MAKE/MODEL/STYLE:	2004 Hyundai XG350 4-Door Sedan
VIN:	KMHFU45E04A273719
DATE OF MANUFACTURE:	March 6, 2003 (SEE CERTIFICATION LABEL)
COLOR:	Red (Bordeaux)

Test Number:	01
Test Date:	February 5, 2004
Target Location:	B-Pillar
Target Code:	BP4
Horizontal Impact Angle:	135°
Vertical Impact Angle:	-10°
Ambient Temperature:	20°C
Relative Humidity:	14
Time of Impact:	10:55
Headform Number:	0805

Impact Point Description (from lower midpoint on midsagittal line)				
On Centerline	8		mm right	x mm left
On Centerline	17		mm up	



POST-IMPACT BP4 HEADFORM (Placard mislabeled Jan., should be Feb.)

Free Motion HIC	667.7
HIC(d)	670.2
Impact Velocity (kph)	23.50
HIC T1 (msec)	1.1
HIC T2 (msec)	9.6

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350 C40500 - BP4

FMH Headform 805

Location: BP4

Test Date: February 05, 2004

Work File: BP4

TEST RESULTS

Lab Temperature: 20 C

HICd: 670.2

Lab Humidity: 14 %

HIC (36ms): 667.7

Velocity at Impact: 23.50 KPH

t1: 1.1 msec

t2: 9.6 msec

Free Flight Distance: 214.34 mm

Duration: 8.5 msec


Average Acceleration: 8.5 g

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Resultant

Max: 108.3 [g] at 0.007 [s]


Min: 0.0 [g] at -0.089 [s]



FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform X Acceleration

Max: 21.1 [g] at -0.025 [s]
Min: -104.0 [g] at 0.003 [s]




CFC_1000

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Y Acceleration

Max: 11.0 [g] at 0.007 [s]
Min: -2.7 [g] at 0.002 [s]



CFC_1000

Time [s]


C40500 - February 05, 2004

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Z Acceleration

Max: 32.1 [g] at 0.006 [s]

Min: -3.4 [g] at -0.012 [s]




C40500 Passenger Side BP4 Impact Plot #3

C40500 - February 05, 2004

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Resultant

Max: 108.3 [g] at 0.007 [s]
Min: 0.1 [g] at -0.011 [s]




C40500 Passenger Side BP4 Impact Plot #4


FMVSS 201U IMPACT TEST - 2004 Hyundai XG350


Max: 23.5 [KPH] at -0.000 [s]
 Min: -7.9 [KPH] at 0.015 [s]

Headform Velocity



C40500 - February 05, 2004






VEHICLE YEAR/MAKE/MODEL/STYLE:	2004 Hyundai XG350 4-Door Sedan
VIN:	KMHFU45E04A273719
DATE OF MANUFACTURE:	March 6, 2003(SEE CERTIFICATION LABEL)
COLOR:	Red (Bordeaux)

Test Number:	02
Test Date:	February 5, 2004
Target Location:	Side Rail Grab Handle
Target Code:	SR3
Horizontal Impact Angle:	90°
Vertical Impact Angle:	41°
Ambient Temperature:	20°C
Relative Humidity:	14
Time of Impact:	11:40
Headform Number:	0355

Impact Point Description (from lower midpoint on midsagittal line)			
On Centerline	17	☒ mm right	☐ mm left
On Centerline	20	mm up	



POST-IMPACT SR3 HEADFORM (Placard mislabeled Jan., should be Feb.)

Free Motion HIC	424.3
HIC(d)	486.5
Impact Velocity (kph)	23.47
HIC T1 (msec)	1.4
HIC T2 (msec)	9.7

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350 C40500 - SR3

FMH Headform 0355

Location: SR3

Test Date: February 05, 2004

Work File: SR3

TEST RESULTS

Lab Temperature: 20 C

HICd: 486.5

Lab Humidity: 14 %

HIC (36ms): 424.3

Velocity at Impact: 23.47 KPH

t1: 1.4 msec

t2: 9.7 msec

Free Flight Distance: 219.82 mm

Duration: 8.2 msec


Average Acceleration: 8.0 g

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Resultant

Max: 95.8 [g] at 0.007 [s]


Min: 0.0 [g] at -0.073 [s]



FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform X Acceleration

Max: 21.6 [g] at -0.026 [s]
Min: -90.7 [g] at 0.007 [s]




C40500 - February 05, 2004

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Y Acceleration

Max: 1.0 [g] at -0.033 [s]
Min: -13.1 [g] at 0.008 [s]




C40500 - February 05, 2004

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Z Acceleration


Max: 31.0 [g] at 0.008 [s]
Min: -2.0 [g] at -0.027 [s]



FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Max: 95.8 [g] at 0.007 [s]
Min: 0.9 [g] at 0.019 [s]

Headform Resultant




C40500 - February 05, 2004

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Max: 23.8 [KPH] at -0.014 [s]

Min: -1.1 [KPH] at 0.021 [s]

Headform Velocity




CFC_180

C40500 - February 05, 2004

FM VSS 20111 040500
04 HYUNDAI X0350 SR3
PRE-TEST 05 JAN 04
HOR 00-MUR 41


PRE-IMPACT SRC (Placed in vehicle Jan. 2004 by (ph))



VEHICLE YEAR/MAKE/MODEL/STYLE:	2004 Hyundai XG350 4-Door Sedan
VIN:	KMHFU45E04A273719
DATE OF MANUFACTURE:	March 6, 2003 (SEE CERTIFICATION LABEL)
COLOR:	Red (Bordeaux)

Test Number:	03
Test Date:	February 5, 2004
Target Location:	Rear Pillar
Target Code:	RP2
Horizontal Impact Angle:	79°
Vertical Impact Angle:	14°
Ambient Temperature:	20°C
Relative Humidity:	14
Time of Impact:	13:30
Headform Number:	1255

Impact Point Description (from lower midpoint on midsagittal line)			
On Centerline	6	mm right	x mm left
On Centerline	23	mm up	



POST-IMPACT RP2 HEADFORM (Placard mislabeled Jan., should be Feb. and 90 should be 79)

Free Motion HIC	546.0
HIC(d)	578.3
Impact Velocity (kph)	23.68
HIC T1 (msec)	4.3
HIC T2 (msec)	13.0

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350 C40500 - RP2

FMH Headform 1255

Location: RP2

Test Date: February 05, 2004

Work File: RP2

TEST RESULTS

Lab Temperature: 20 C

HICd: 578.3

Lab Humidity: 14 %

HIC (36ms): 546.0

Velocity at Impact: 23.68 KPH

t1: 4.3 msec

t2: 13.0 msec

Duration: 8.7 msec

Free Flight Distance: 219.28 mm


Average Acceleration: 8.9 g

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Resultant

Max: 106.7 [g] at 0.008 [s]


Min: 0.0 [g] at -0.068 [s]



FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform X Acceleration

Max: 21.5 [g] at -0.024 [s]
Min: -103.6 [g] at 0.008 [s]



CFC_1000


Time [s]

C40500 - February 05, 2004

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Y Acceleration


Max: 1.5 [g] at 0.002 [s]
Min: -8.3 [g] at 0.006 [s]



C40500 - February 05, 2004

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350
Headform Z Acceleration

Max: 32.0 [g] at 0.010 [s]
Min: -4.8 [g] at 0.004 [s]




C40500 - February 05, 2004

C40500 Passenger Side RP2 Impact Plot #3

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Max: 106.7 [g] at 0.008 [s]
Min: 0.3 [g] at 0.027 [s]

Headform Resultant




C40500 Passenger Side RP2 Impact Plot #4

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Max: 23.7 [KPH] at -0.014 [s]
Min: -10.0 [KPH] at 0.050 [s]

Headform Velocity



C40500 Passenger Side RP2 Impact Plot #5

PM VSS 201U C40500
04 HYUNDAI XC350 R92
PRE TEST 05 JAN 04
HOR 60 VER 14

07-00-05

FM VSS 201U C40500
04 HYUNDAI XG350 RP2
POST TEST 05 JAN 04
HCR 90 VER 14

POST-IMPACT RUC (Phonebook not needed Jan. should be Feb. and 90 should be 15)

ST70-06

VEHICLE YEAR/MAKE/MODEL/STYLE:	2004 Hyundai XG350 4-Door Sedan
VIN:	KMHFU45E04A273719
DATE OF MANUFACTURE:	March 6, 2003(SBS CERTIFICATION LABEL)
COLOR:	Red (Bordeaux)

Test Number:	04
Test Date:	February 5, 2004
Target Location:	B-Pillar
Target Code:	BP1
Horizontal Impact Angle:	90°
Vertical Impact Angle:	22°
Ambient Temperature:	20°C
Relative Humidity:	14
Time of Impact:	14:00
Headform Number:	0642

Impact Point Description (from lower midpoint on midsagittal line)			
On Centerline	0	mm right	mm left
On Centerline	35	mm up	



POST-IMPACT BP1 HEADFORM (Placard mislabeled Jan., should be Feb.)

Free Motion HIC	812.0
HIC(d)	779.1
Impact Velocity (kph)	23.51
HIC T1 (msec)	2.2
HIC T2 (msec)	10.1

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350 C40500 - BP1

FMH Headform 0642

Location: BP1

Test Date: February 05, 2004

Work File: BP1

TEST RESULTS

Lab Temperature: 20 C

HICd: 779.1

Lab Humidity: 14 %

HIC (36ms): 812.0

Velocity at Impact: 23.51 KPH

t1: 2.2 msec

t2: 10.1 msec

Free Flight Distance: 218.07 mm

Duration: 7.8 msec


Average Acceleration: 9.8 g

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Resultant

Max: 133.3 [g] at 0.006 [s]


Min: 0.0 [g] at -0.094 [s]



FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform X Acceleration

Max: 100.9 [g] at 0.041 [s]
Min: -128.7 [g] at 0.006 [s]




C40500 - February 05, 2004

C40500 Passenger Side BPI Impact Plot #1

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Y Acceleration

Max: 41.7 [g] at 0.041 [s]
Min: -34.8 [g] at 0.040 [s]



CFC_1000

Time [s]


C40500 - February 05, 2004

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Z Acceleration

Max: 58.2 [g] at 0.041 [s]

Min: -31.3 [g] at 0.041 [s]



CFC_1000


Time [s]

C40500 - February 05, 2004

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Resultant

Max: 133.3 [g] at 0.006 [s]
Min: 0.2 [g] at 0.048 [s]




C40500 Passenger Side BP1 Impact Plot #4


FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Velocity

Max: 23.7 [KPH] at -0.014 [s]

Min: -10.1 [KPH] at 0.038 [s]






PBS IMPACT HDI (Passes indicated in red should be F&E)



VEHICLE YEAR/MAKE/MODEL/STYLE:	2004 Hyundai XG350 4-Door Sedan
VIN:	KMHFU45E04A273719
DATE OF MANUFACTURE:	March 6, 2004(SEE CERTIFICATION LABEL)
COLOR:	Red (Bordeaux)

Test Number:	05
Test Date:	February 5, 2004
Target Location:	A-Pillar
Target Code:	AP3
Horizontal Impact Angle:	134°
Vertical Impact Angle:	45°
Ambient Temperature:	20°C
Relative Humidity:	14
Time of Impact:	14:30
Headform Number:	0062

Impact Point Description (from lower midpoint on midsagittal line)			
On Centerline	0	mm right	mm left
On Centerline	15	mm up	



POST-IMPACT AP3 HEADFORM (Placard mislabeled Jan., should be Feb.)

Free Motion HIC	512.6
HIC(d)	553.1
Impact Velocity (kph)	23.35
HIC T1 (msec)	1.2
HIC T2 (msec)	11.7

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350 C40500 - AP3

FMH Headform 0062

Location: AP3

Test Date: February 05, 2004

Work File: AP3

TEST RESULTS

Lab Temperature: 20 C

HICd: 553.1

Lab Humidity: 14 %

HIC (36ms): 512.6

Velocity at Impact: 23.35 KPH

t1: 1.2 msec

t2: 11.7 msec

Free Flight Distance: 221.32 mm

Duration: 10.4 msec


Average Acceleration: 9.9 g

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Resultant

Max: 97.1 [g] at 0.005 [s]


Min: 0.0 [g] at -0.066 [s]



FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform X Acceleration

Max: 22.9 [g] at -0.025 [s]
Min: -95.8 [g] at 0.005 [s]




C40500 - February 05, 2004

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Y Acceleration

Max: 16.1 [g] at 0.010 [s]
Min: -14.1 [g] at 0.005 [s]




C40500 Passenger Side AP3 Impact Plot #2

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Z Acceleration


Max: 27.7 [g] at 0.009 [s]
Min: -5.3 [g] at 0.049 [s]



FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Resultant


Max: 97.1 [g] at 0.005 [s]
Min: 0.4 [g] at 0.039 [s]



FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Max: 23.8 [KPH] at -0.014 [s]
 Min: -8.1 [KPH] at 0.045 [s]

Headform Velocity




CFC_180

Time [s]

C40500 - February 05, 2004

FMVSS 201U / C40500
04 HYUNDAI XG350 AP3
PRE TEST 05 JAN 04
HCR 134 VER 45

PRE-IMPACT AP3 (Discord and label line should be FAI.)



POST-IMPACT XPS (Pinned Reinforced In. - Aligned N/E/W)

VEHICLE YEAR/MAKE/MODEL/STYLE:	2004 Hyundai XG350 4-Door Sedan
VIN:	KMHFU45E04A273719
DATE OF MANUFACTURE:	March 6, 2003(SEE CERTIFICATION LABEL)
COLOR:	Red (Bordeaux)

Test Number:	06
Test Date:	February 5, 2004
Target Location:	A-Pillar
Target Code:	AP1
Horizontal Impact Angle:	122°
Vertical Impact Angle:	42°
Ambient Temperature:	20°C
Relative Humidity:	14
Time of Impact:	15:15
Headform Number:	0805

Impact Point Description (from lower midpoint on midsagittal line)			
On Centerline	10	☒ mm right	☐ mm left
On Centerline	11	mm up	



POST-IMPACT AP1 HEADFORM

Free Motion HIC	953.5
HIC(d)	885.8
Impact Velocity (kph)	23.74
HIC T1 (msec)	3.5
HIC T2 (msec)	8.8

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350 C40500 - AP1

FMH Headform 0805

Location: AP1

Test Date: February 05, 2004

Work File: AP1

TEST RESULTS

Lab Temperature: 20 C

HICd: 885.8

Lab Humidity: 14 %

HIC (36ms): 953.5

Velocity at Impact: 23.74 KPH

t1: 3.5 msec

t2: 8.7 msec

Free Flight Distance: 218.21 mm

Duration: 5.2 msec


Average Acceleration: 9.8 g

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Resultant

Max: 170.0 [g] at 0.006 [s]


Min: 0.0 [g] at -0.066 [s]



FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform X Acceleration

Max: 72.5 [g] at 0.040 [s]
Min: -167.1 [g] at 0.006 [s]




C40500 - February 05, 2004

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Y Acceleration

Max: 32.3 [g] at 0.040 [s]
Min: -24.0 [g] at 0.040 [s]




C40500 - February 05, 2004

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Z Acceleration

Max: 69.7 [g] at 0.040 [s]
Min: -25.3 [g] at 0.041 [s]




C40500 Passenger Side AP1 Impact Plot #3

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Max: 170.0 [g] at 0.006 [s]
Min: 0.4 [g] at 0.049 [s]

Headform Resultant




C40500 - February 05, 2004

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Velocity

Max: 24.0 [KPH] at -0.013 [s]
Min: -8.6 [KPH] at 0.038 [s]



C40500 Passenger Side AP1 Impact Plot #5



PRE-IMPACT A2

8/30/06

FM VSS 201U C40500
04 HYUNDAI XG350 A
POST TEST 05 FEB 04
HOR 12.2 VER 42


POST-IMPACT AM

8756-05

VEHICLE YEAR/MAKE/MODEL/STYLE:	2004 Hyundai XG350 4-Door Sedan
VIN:	KMHFU45E04A273719
DATE OF MANUFACTURE:	March 6, 2003 (SEE CERTIFICATION LABEL)
COLOR:	Red (Bordeaux)

Test Number:	07
Test Date:	February 6, 2004
Target Location:	B-Pillar Seat Belt Anchorage
Target Code:	BP2
Horizontal Impact Angle:	270°
Vertical Impact Angle:	7°
Ambient Temperature:	22°C
Relative Humidity:	20
Time of Impact:	9:45
Headform Number:	0805

Impact Point Description (from lower midpoint on midsagittal line)			
On Centerline	3	mm right	x mm left
On Centerline	8	mm up	



POST-IMPACT BP2 HEADFORM

Free Motion HIC	854.2
HIC(d)	810.9
Impact Velocity (kph)	23.59
HIC T1 (msec)	1.7
HIC T2 (msec)	7.7

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350 C40500 - BP2

FMH Headform 805

Location: BP2

Test Date: February 06, 2004

Work File: BP2

TEST RESULTS

Lab Temperature: 22 C

HICd: 810.9

Lab Humidity: 20 %

HIC (36ms): 854.2

Velocity at Impact: 23.59 KPH

t1: 1.7 msec

t2: 7.7 msec

Free Flight Distance: 214.61 mm

Duration: 6.0 msec


Average Acceleration: 9.4 g

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Resultant

Max: 151.3 [g] at 0.005 [s]

Min: 0.0 [g] at -0.074 [s]




FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform X Acceleration

Max: 68.2 [g] at 0.035 [s]

Min: -145.9 [g] at 0.005 [s]



CFC_1000

-0.025

0.025

0.05


Time [s]

C40500 - February 06, 2004

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Y Acceleration

Max: 16.5 [g] at 0.034 [s]
Min: -34.1 [g] at 0.033 [s]



C40500 - February 06, 2004


C40500 Driver Side BP2 Impact Plot #2

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Z Acceleration

Max: 52.3 [g] at 0.035 [s]

Min: -26.1 [g] at 0.034 [s]



CFC_1000

Time [s]


C40500 - February 06, 2004

C40500 Driver Side BP2 Impact Plot #3

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Max: 151.3 [g] at 0.005 [s]
Min: 0.3 [g] at -0.011 [s]

Headform Resultant




C40500 - February 06, 2004

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Velocity

Max: 23.6 [KPH] at -0.013 [s]
Min: -9.0 [KPH] at 0.032 [s]



C40500 Driver Side BP2 Impact Plot #5



PHOTOGRAPH BY


S770-06



VEHICLE YEAR/MAKE/MODEL/STYLE:	2004 Hyundai XG350 4-Door Sedan
VIN:	KMHFU45E04A273719
DATE OF MANUFACTURE:	March 6, 2003(SEE CERTIFICATION LABEL)
COLOR:	Red (Bordeaux)

Test Number:	08
Test Date:	February 6, 2004
Target Location:	Upper Roof
Target Code:	URBP
Horizontal Impact Angle:	270°
Vertical Impact Angle:	47°
Ambient Temperature:	22°C
Relative Humidity:	20
Time of Impact:	10:10
Headform Number:	0355

Impact Point Description (from lower midpoint on midsagittal line)				
On Centerline	5		mm right	mm left
On Centerline	49		mm up	



POST-IMPACT URBP HEADFORM

Free Motion HIC	848.6
HIC(d)	806.7
Impact Velocity (kph)	23.42
HIC T1 (msec)	3.3
HIC T2 (msec)	10.7

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350 C40500 - URBP

FMH Headform 0355

Location: URBP

Test Date: February 06, 2004

Work File: URBP

TEST RESULTS

Lab Temperature: 22 C

HICd: 806.7

Lab Humidity: 20 %

HIC (36ms): 848.6

Velocity at Impact: 23.42 KPH

t1: 3.3 msec

t2: 10.7 msec

Free Flight Distance: 225.84 mm

Duration: 7.4 msec


Average Acceleration: 11.5 g

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Resultant

Max: 131.8 [g] at 0.007 [s]

Min: 0.0 [g] at -0.097 [s]




FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform X Acceleration

Max: 83.8 [g] at 0.045 [s]

Min: -131.8 [g] at 0.007 [s]




C40500 - February 06, 2004

C40500 Driver Side URBP Impact Plot #1

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350
Headform Y Acceleration

Max: 44.4 [g] at 0.045 [s]
Min: -8.7 [g] at 0.046 [s]




C40500 Driver Side URBP Impact Plot #2

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Z Acceleration

Max: 72.8 [g] at 0.045 [s]

Min: -12.3 [g] at 0.045 [s]




C40500 - February 06, 2004

C40500 Driver Side URBP Impact Plot #3

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Resultant

Max: 131.8 [g] at 0.007 [s]
Min: 0.5 [g] at 0.047 [s]




C40500 - February 06, 2004

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Velocity

Max: 23.9 [KPH] at -0.015 [s]
Min: -11.3 [KPH] at 0.044 [s]



CFC_180

-0.025

Time [s]

0.025

C40500 - February 06, 2004



PRE-IMPACT VIEW


9790-05



VEHICLE YEAR/MAKE/MODEL/STYLE:	2004 Hyundai XG350 4-Door Sedan
VIN:	KMHFU45E04A273719
DATE OF MANUFACTURE:	March 6, 2003 (SEE CERTIFICATION LABEL)
COLOR:	Red (Bordeaux)

Test Number:	09
Test Date:	February 6, 2004
Target Location:	Upper Roof
Target Code:	URRP
Horizontal Impact Angle:	309°
Vertical Impact Angle:	47°
Ambient Temperature:	22°C
Relative Humidity:	20
Time of Impact:	10:35
Headform Number:	0062

Impact Point Description (from lower midpoint on midsagittal line)			
On Centerline	3	mm right	mm left
On Centerline	22	mm up	



POST-IMPACT URRP HEADFORM

Free Motion HIC	981.0
HIC(d)	906.5
Impact Velocity (kph)	23.38
HIC T1 (msec)	4.6
HIC T2 (msec)	9.8

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350 C40500 - URRP

FMH Headform 0062

Location: URRP

Test Date: February 06, 2004

Work File: URRP

TEST RESULTS

Lab Temperature: 22 C

HICd: 906.5

Lab Humidity: 20 %

HIC (36ms): 981.0

Velocity at Impact: 23.38 KPH

t1: 4.6 msec

t2: 9.8 msec

Free Flight Distance: 206.69 mm

Duration: 5.2 msec


Average Acceleration: 9.9 g

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Resultant


Max: 209.5 [g] at 0.040 [s]

Min: 0.0 [g] at -0.058 [s]



FMVSS 201U IMPACT TEST - 2004 Hyundai XG350
Headform X Acceleration

Max: 208.5 [g] at 0.040 [s]
Min: -161.3 [g] at 0.007 [s]




C40500 Driver Side URRP Impact Plot #1

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Y Acceleration

Max: 21.6 [g] at 0.041 [s]

Min: -23.3 [g] at 0.041 [s]




C40500 Driver Side URRP Impact Plot #2

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Z Acceleration

Max: 61.6 [g] at 0.041 [s]

Min: -41.1 [g] at 0.041 [s]




C40500 - February 06, 2004

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Max: 209.5 [g] at 0.040 [s]
Min: 0.6 [g] at 0.029 [s]

Headform Resultant




C40500 - February 06, 2004

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Max: 23.7 [KPH] at -0.013 [s]
Min: -10.4 [KPH] at 0.039 [s]

Headform Velocity



CFC_180

Time [s]

C40500 - February 06, 2004

FMVSS 201U C40500
04 HYUNDAI XG350 URRP
PRE TEST 06 FEB 04
HOR 309 VER 47


PRE-IMPACT URRP

3730-06

VEHICLE YEAR/MAKE/MODEL/STYLE:	2004 Hyundai XG350 4-Door Sedan
VIN:	KMHFU45E04A273719
DATE OF MANUFACTURE:	March 6, 2003 (SEE CERTIFICATION LABEL)
COLOR:	Red (Bordeaux)

Test Number:	10
Test Date:	February 6, 2004
Target Location:	A-Pillar
Target Code:	AP2
Horizontal Impact Angle:	218°
Vertical Impact Angle:	43°
Ambient Temperature:	22°C
Relative Humidity:	20
Time of Impact:	11:15
Headform Number:	0642

Impact Point Description (from lower midpoint on midsagittal line)			
On Centerline	7	x	mm right ☐ mm left
On Centerline	21		mm up



POST-IMPACT AP2 HEADFORM

Free Motion HIC	496.2
HIC(d)	540.8
Impact Velocity (kph)	23.59
HIC T1 (msec)	1.6
HIC T2 (msec)	10.3

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350 C40500 - AP2

FMH Headform 0642

Location: AP2

Test Date: February 06, 2004

Work File: AP2

TEST RESULTS

Lab Temperature: 22 C

HICd: 540.8

Lab Humidity: 20 %

HIC (36ms): 496.2

Velocity at Impact: 23.59 KPH

t1: 1.6 msec

t2: 10.3 msec

Free Flight Distance: 215.74 mm

Duration: 8.6 msec


Average Acceleration: 10.4 g

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Resultant

Max: 100.6 [g] at 0.008 [s]


Min: 0.0 [g] at -0.090 [s]



FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform X Acceleration


Max: 22.7 [g] at -0.024 [s]
Min: -97.5 [g] at 0.008 [s]



C40500 Driver Side AP2 Impact Plot #1

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350
Headform Y Acceleration

Max: 11.0 [g] at 0.005 [s]
Min: -10.7 [g] at 0.010 [s]




C40500 - February 06, 2004

C40500 Driver Side AP2 Impact Plot #2

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350

Headform Z Acceleration

Max: 24.3 [g] at 0.008 [s]
Min: -2.3 [g] at -0.016 [s]




C40500 Driver Side AP2 Impact Plot #3

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350


Headform Resultant

Max: 100.6 [g] at 0.008 [s]
Min: 0.3 [g] at 0.029 [s]



C40500 Driver Side AP2 Impact Plot #4

FMVSS 201U IMPACT TEST - 2004 Hyundai XG350
Headform Velocity
Max: 23.9 [KPH] at -0.014 [s]
Min: -6.3 [KPH] at 0.050 [s]



C40500 Driver Side AP2 Impact Plot #5



PRE-IMPACT

8730:05

FM VSS 2010 040500
04 HYUNDAI XG350 AP2
POST TEST 06 FEB 04
HOR 218 VER 43

POST-IMPACT AP2

8750-06

APPENDIX A
PHOTOGRAPHS

PHOTOGRAPHS

FIGURE	VIEW
A-1	LEFT SIDE VIEW OF VEHICLE
A-2	RIGHT SIDE VIEW OF VEHICLE
A-3	3/4 FRONTAL VIEW FROM LEFT SIDE OF VEHICLE
A-4	3/4 REAR VIEW FROM RIGHT SIDE OF VEHICLE
A-5	VEHICLE'S CERTIFICATION LABEL
A-6	VEHICLE'S TIRE INFORMATION LABEL
A-7	PRE-TEST DRIVER SIDE A-PILLAR
A-8	PRE-TEST DRIVER SIDE FRONT HEADER
A-9	PRE-TEST DRIVER SIDE SIDE RAIL
A-10	PRE-TEST DRIVER SIDE B-PILLAR
A-11	PRE-TEST DRIVER SIDE REAR PILLAR
A-12	PRE-TEST PASSENGER SIDE A-PILLAR
A-13	PRE-TEST PASSENGER SIDE FRONT HEADER
A-14	PRE-TEST PASSENGER SIDE SIDE RAIL
A-15	PRE-TEST PASSENGER SIDE B-PILLAR
A-16	PRE-TEST PASSENGER SIDE REAR PILLAR
A-17	POST-TEST DRIVER SIDE A-PILLAR
A-18	POST-TEST DRIVER FRONT HEADER
A-19	POST-TEST DRIVER SIDE SIDE RAIL
A-20	POST-TEST DRIVER SIDE B-PILLAR
A-21	POST-TEST DRIVER SIDE REAR PILLAR
A-22	POST-TEST PASSENGER SIDE A-PILLAR
A-23	POST-TEST PASSENGER FRONT HEADER
A-24	POST-TEST PASSENGER SIDE SIDE RAIL
A-25	POST-TEST PASSENGER SIDE B-PILLAR
A-26	POST-TEST PASSENGER SIDE REAR PILLAR



Figure A-1 : LEFT SIDE VIEW OF VEHICLE

2-4

8710-00



Figure A-2 RIGHT SIDE VIEW OF VEHICLE



Figure A-3 3/4 FRONTAL VIEW FROM LEFT SIDE OF VEHICLE



Figure A-4. 3/4 REAR VIEW FROM RIGHT SIDE OF VEHICLE




Figure A-3: VEHICLE'S CERTIFICATION LABEL




Figure 4-6. VEHICLE'S TIRE INFORMATION LABEL




Figure A-7 | PRE-TEST DRIVER SIDE A-PILLAR




Figure A-8. PRE-TEST DRIVER SIDE FRONT ENDER




Figure A.9 PRE TEST DRIVER SIDE SIDE RAIL



Figure A-10: PRE-TEST DRIVER'S SIDE COLLAR




Figure A.11. PRE-TEXT DRIVER SIDE REAR PILLAR




Figure A-12 PRE-TEST PASSENGER SIDE A-PILLAR




Figure A-13. PRE-TEST PASSENGER SIDE FRONT HEADER




Figure A-14 PRE-TEST PASSENGER SIDE SIDE RAIL




Figure A-15 PAS-TEST PASSENGER SIDE B-PILLAR




Figure A-16: PRE-TEST PASSENGER SIDE REAR PILLAR




Figure A-17. POST-TEST DRIVER SIDE A-PILLAR

FM VSS 201U C40500
04 HYUNDAI XG350
POST TEST 05 FEB 04

Figure A-18 POST-TEST DRIVER SIDE FRONT HEADER

A-31

07-03-05




Figure A-19 POST-TEST DRIVER SIDE SIDE RAIL



Figure A-20: POST-TEST DRIVER SIDE B-PILLAR

FM VSS 201U C40500
04 HYUNDAI KG350
POST TEST 06 FEB 04

View A-21 POST-TEST DRIVER SIDE REAR PILLAR




Figure A-22 POST TEST PASSENGER SIDE A-PILLAR




Figure A-25. POST TEST PASSENGER SIDE FRONT HEADER




Figure A-04 POST-TEST PASSENGER SIDE SIDE RAIL




Figure A-23 POST TEST PASSENGER SIDE B-PILLAR



Figure A-26. POST-TEST PASSENGER SIDE REAR PILLAR

APPENDIX B

PART 572L PERFORMANCE CALIBRATION IN SUPPORT OF VEHICLE SAFETY COMPLIANCE TESTING FOR OCCUPANT PROTECTION IN INTERIOR IMPACT

Appendix B contains the results from certification tests performed on the Free Motion Headforms utilized in this test program. The results indicate that the headforms meet all of the performance specifications given in 49 CFR Part 572 Subpart L.

The tests were conducted at the Dummy Certification Test Facility of Veridian Engineering. A summary of the test results are included in this Appendix.

**PART 572L
HEAD DROP PRE-TEST**

MANUFACTURER:		FIRST TECHNOLOGY SAFETY SYSTEMS
SERIAL NUMBER:		0642
CALIBRATION DATE:		February 4, 2004
TEST PARAMETER	SPECIFICATION	TEST RESULTS
TEMPERATURE	19°C to 26°C	23
RELATIVE HUMIDITY	10% to 70%	16
PEAK RESULTANT ACCELERATION	225 Gs to 275 Gs	269.8
PEAK LATERAL ACCELERATION	15 Gs Maximum	9.7
IS ACCELERATION CURVE UNIMODAL?	YES	YES

HEAD ACCELEROMETER CALIBRATION INFORMATION


LD. NUMBER	MANUFACTURER	MODEL NUMBER	SERIAL NUMBER	DATE OF LAST CALIBRATION	DATE OF NEXT CALIBRATION
1 - LONGITUDINAL	ENDEVCO	7264-2000T	J24876	08/22/03	02/23/04
2 - LATERAL	ENDEVCO	7264-2000T	J33038	08/22/03	02/23/04
3 - VERTICAL	ENDEVCO	7264-2000T	J31009	08/22/03	02/23/04

REMARKS:

FMVSS 201U - Headform Calibration Drops

Headform X Acceleration


Max: 11.5 [g] at 0.004 [s]
Min: -239.2 [g] at 0.001 [s]



FMVSS 201U - Headform Calibration Drops

Max: 9.7 [g] at 0.002 [s]
Min: -1.3 [g] at 0.005 [s]


Headform Y Acceleration



FMVSS 201U - Headform Calibration Drops

Max: 124.4 [g] at 0.002 [s]
Min: -0.3 [g] at 0.019 [s]


Headform Z Acceleration



FMVSS 201U - Headform Calibration Drops

Max: 269.8 [g] at 0.002 [s]
Min: 0.0 [g] at -0.001 [s]

Headform Resultant



**PART 572L
HEAD DROP PRE-TEST**

MANUFACTURER:		FIRST TECHNOLOGY SAFETY SYSTEMS	
SERIAL NUMBER:		0062	
CALIBRATION DATE:		February 4, 2004	
TEST PARAMETER	SPECIFICATION		TEST RESULTS
TEMPERATURE	19°C to 26°C		23
RELATIVE HUMIDITY	10% to 70%		16
PEAK RESULTANT ACCELERATION	225 Gs to 275 Gs		254.7
PEAK LATERAL ACCELERATION	15 Gs Maximum		7.3
IS ACCELERATION CURVE UNIMODAL?	YES		YES

HEAD ACCELEROMETER CALIBRATION INFORMATION


ID. NUMBER	MANUFACTURER	MODEL NUMBER	SERIAL NUMBER	DATE OF LAST CALIBRATION	DATE OF NEXT CALIBRATION
1 - LONGITUDINAL	ENDEVCO	7264-2000T	J33127	08/22/03	02/23/04
2 - LATERAL	ENDEVCO	7264-2000T	J33019	08/22/03	02/23/04
3 - VERTICAL	ENDEVCO	7264-2000T	J32782	08/22/03	02/23/04

REMARKS:

FMVSS 201U - Headform Calibration Drops

Max: 1.0 [g] at 0.005 [s]
Min: -221.5 [g] at 0.001 [s]


Headform X Acceleration



FMVSS 201U - Headform Calibration Drops

Max: 0.8 [g] at 0.004 [s]
Min: -7.3 [g] at 0.001 [s]

Headform Y Acceleration




C40500 - February 04, 2004

FMVSS 201U - Headform Calibration Drops

Max: 125.5 [g] at 0.001 [s]
Min: -0.5 [g] at 0.007 [s]


Headform Z Acceleration



FMVSS 201U - Headform Calibration Drops

Max: 254.7 [g] at 0.001 [s]
Min: 0.0 [g] at -0.042 [s]

Headform Resultant



C40500 - February 04, 2004

**PART 572L
HEAD DROP PRE-TEST**

MANUFACTURER:		FIRST TECHNOLOGY SAFETY SYSTEMS
SERIAL NUMBER:		805
CALIBRATION DATE:		February 4, 2004
TEST PARAMETER	SPECIFICATION	TEST RESULTS
TEMPERATURE	19°C to 25°C	23
RELATIVE HUMIDITY	10% to 70%	16
PEAK RESULTANT ACCELERATION	225 Gs to 275 Gs	261.7
PEAK LATERAL ACCELERATION	15 Gs Maximum	4.5
IS ACCELERATION CURVE UNIMODAL?	YES	YES

HEAD ACCELEROMETER CALIBRATION INFORMATION


ID NUMBER	MANUFACTURER	MODEL NUMBER	SERIAL NUMBER	DATE OF LAST CALIBRATION	DATE OF NEXT CALIBRATION
1 - LONGITUDINAL	ENDEVCO	7264-2000T	J38127	08/22/03	02/23/04
2 - LATERAL	ENDEVCO	7264-2000T	J37980	08/22/03	02/23/04
3 - VERTICAL	ENDEVCO	7264-2000T	J37854	08/22/03	02/23/04

REMARKS:

FMVSS 201U - Headform Calibration Drops

Max: 1.0 [g] at 0.035 [s]
Min: -228.4 [g] at 0.001 [s]

Headform X Acceleration



CFC_1000


Time [s]

C40500 - February 04, 2004

FMVSS 201U - Headform Calibration Drops

Max: 0.7 [g] at 0.011 [s]
Min: -4.5 [g] at 0.001 [s]

Headform Y Acceleration




C40500 - February 04, 2004

FMVSS 201U - Headform Calibration Drops

Max: 127.9 [g] at 0.001 [s]
Min: -0.9 [g] at 0.005 [s]

Headform Z Acceleration




C40500 - February 04, 2004

FMVSS 201U - Headform Calibration Drops

Max: 261.7 [g] at 0.001 [s]
Min: 0.0 [g] at -0.022 [s]

Headform Resultant



C40500 - February 04, 2004

**PART 572L
HEAD DROP PRE-TEST**

MANUFACTURER:		FIRST TECHNOLOGY SAFETY SYSTEMS	
SERIAL NUMBER:		0355	
CALIBRATION DATE:		February 4, 2004	
TEST PARAMETER	SPECIFICATION	TEST RESULTS	
TEMPERATURE	19°C to 26°C	23	
RELATIVE HUMIDITY	10% to 70%	16	
PEAK RESULTANT ACCELERATION	225 G_s to 275 G_s	240.6	
PEAK LATERAL ACCELERATION	35 G_s Maximum	7.8	
IS ACCELERATION CURVE UNIMODAL?	YES	YES	

HEAD ACCELEROMETER CALIBRATION INFORMATION


I.D. NUMBER	MANUFACTURER	MODEL NUMBER	SERIAL NUMBER	DATE OF LAST CALIBRATION	DATE OF NEXT CALIBRATION
1 - LONGITUDINAL	ENDEVCO	7264-2000T	J28671	08/22/03	02/23/04
2 - LATERAL	ENDEVCO	7264-2000T	J32779	08/22/03	02/23/04
3 - VERTICAL	ENDEVCO	7264-2000T	J25854	08/22/03	02/23/04

REMARKS:

FMVSS 201U - Headform Calibration Drops

Max: 0.5 [g] at 0.014 [s]
Min: -215.2 [g] at 0.001 [s]

Headform X Acceleration




C40500 - February 04, 2004

FMVSS 201U - Headform Calibration Drops

Max: 0.1 [g] at 0.006 [s]
Min: -7.8 [g] at 0.001 [s]

Headform Y Acceleration




C40500 - February 04, 2004

FMVSS 201U - Headform Calibration Drops

Max: 108.3 [g] at 0.001 [s]
Min: -1.3 [g] at 0.007 [s]

Headform Z Acceleration




C40500 - February 04, 2004

FMVSS 201U - Headform Calibration Drops

Max: 240.6 [g] at 0.001 [s]
Min: 0.0 [g] at -0.014 [s]

Headform Resultant



CFC_1000

Time [s]

0.025

0.05

C40500 - February 04, 2004

**PART 572L
HEAD DROP PRE-TEST**

MANUFACTURER:		FIRST TECHNOLOGY SAFETY SYSTEMS	
SERIAL NUMBER:		1255	
CALIBRATION DATE:		February 4, 2004	
TEST PARAMETER	SPECIFICATION	TEST RESULTS	
TEMPERATURE	19°C to 26°C	23	
RELATIVE HUMIDITY	10% to 70%	16	
PEAK RESULTANT ACCELERATION	225 Gs to 275 Gs	267.3	
PEAK LATERAL ACCELERATION	15 Gs Maximum	4.5	
IS ACCELERATION CURVE UNIMODAL?	YES	YES	

HEAD ACCELEROMETER CALIBRATION INFORMATION


I.D. NUMBER	MANUFACTURER	MODEL NUMBER	SERIAL NUMBER	DATE OF LAST CALIBRATION	DATE OF NEXT CALIBRATION
1 - LONGITUDINAL	ENDEVCO	7264-2800T	J41006	08/22/03	02/23/04
2 - LATERAL	ENDEVCO	7264-2800T	J40994	08/22/03	02/23/04
3 - VERTICAL	ENDEVCO	7264-2800T	J41007	08/22/03	02/23/04

REMARKS:

FMVSS 201U - Headform Calibration Drops

Max: 10.2 [g] at 0.004 [s]
Min: -240.0 [g] at 0.002 [s]


Headform X Acceleration



FMVSS 201U - Headform Calibration Drops

Max: 4.5 [g] at 0.002 [s]
Min: -1.6 [g] at 0.004 [s]

Headform Y Acceleration




C40500 - February 04, 2004

FMVSS 201U - Headform Calibration Drops

Max: 117.7 [g] at 0.002 [s]
Min: -0.9 [g] at 0.009 [s]


Headform Z Acceleration



FMVSS 201U - Headform Calibration Drops

Max: 267.3 [g] at 0.002 [s]
Min: 0.0 [g] at -0.015 [s]

Headform Resultant



C40500 - February 04, 2004

**PART 572L
HEAD DROP POST-TEST**

MANUFACTURER:		FIRST TECHNOLOGY SAFETY SYSTEMS
SERIAL NUMBER:		0642
CALIBRATION DATE:		February 11, 2004
TEST PARAMETER	SPECIFICATION	TEST RESULTS
TEMPERATURE	19°C to 26°C	24
RELATIVE HUMIDITY	10% to 70%	18
PEAK RESULTANT ACCELERATION	225 Gs to 275 Gs	227.8
PEAK LATERAL ACCELERATION	15 Gs Maximum	2.6
IS ACCELERATION CURVE UNIMODAL?	YES	YES

HEAD ACCELEROMETER CALIBRATION INFORMATION


ID NUMBER	MANUFACTURER	MODEL NUMBER	SERIAL NUMBER	DATE OF LAST CALIBRATION	DATE OF NEXT CALIBRATION
1 - LONGITUDINAL	ENDEVCO	7264-3000T	J24876	08/22/03	02/23/04
2 - LATERAL	ENDEVCO	7264-3000T	J33030	08/22/03	02/23/04
3 - VERTICAL	ENDEVCO	7264-2000T	J31809	08/22/03	02/23/04

REMARKS:

FMVSS 201U - Headform Calibration Drops

Max: 7.3 [g] at 0.004 [s]
Min: -202.0 [g] at 0.002 [s]

Headform X Acceleration




C40500 - February 11, 2004

FMVSS 201U - Headform Calibration Drops

Max: 2.6 [g] at 0.003 [s]
Min: -2.3 [g] at 0.002 [s]

Headform Y Acceleration




C40500 - February 11, 2004

FMVSS 201U - Headform Calibration Drops

Max: 105.4 [g] at 0.002 [s]
Min: -0.3 [g] at 0.018 [s]

Headform Z Acceleration




C40500 - February 11, 2004

FMVSS 201U - Headform Calibration Drops

Max: 227.8 [g] at 0.002 [s]
Min: 0.0 [g] at -0.001 [s]

Headform Resultant



C40500 - February 11, 2004

**PART 571L
HEAD DROP POST-TEST**

MANUFACTURER:		FIRST TECHNOLOGY SAFETY SYSTEMS
SERIAL NUMBER:		0062
CALIBRATION DATE:		February 11, 2004
TEST PARAMETER	SPECIFICATION	TEST RESULTS
TEMPERATURE	19°C to 26°C	24
RELATIVE HUMIDITY	10% to 70%	18
PEAK RESULTANT ACCELERATION	125 Gs to 275 Gs	234.8
PEAK LATERAL ACCELERATION	15 Gs Maximum	1.6
IS ACCELERATION CURVE UNIMODAL?	YES	YES

HEAD ACCELEROMETER CALIBRATION INFORMATION


ID. NUMBER	MANUFACTURER	MODEL NUMBER	SERIAL NUMBER	DATE OF LAST CALIBRATION	DATE OF NEXT CALIBRATION
1 - LONGITUDINAL	ENDEVCO	7264-2000T	J33127	08/22/03	02/23/04
2 - LATERAL	ENDEVCO	7264-2000T	J33019	08/22/03	02/23/04
3 - VERTICAL	ENDEVCO	7264-2000T	J32782	08/22/03	02/23/04

REMARKS:

FMVSS 201U - Headform Calibration Drops

Max: 1.5 [g] at 0.006 [s]
 Min: -206.3 [g] at 0.001 [s]

Headform X Acceleration




C40500 - February 11, 2004

FMVSS 201U - Headform Calibration Drops

Headform Y Acceleration


Max: 0.9 [g] at 0.004 [s]
Min: -2.6 [g] at 0.001 [s]



FMVSS 201U - Headform Calibration Drops

Max: 112.6 [g] at 0.001 [s]
Min: -0.9 [g] at 0.007 [s]

Headform Z Acceleration




C40500 - February 11, 2004

FMVSS 201U - Headform Calibration Drops

Max: 234.8 [g] at 0.001 [s]
Min: 0.0 [g] at -0.032 [s]

Headform Resultant



C40500 - February 11, 2004

**PART 572L
HEAD DROP POST-TEST**

MANUFACTURER:		FIRST TECHNOLOGY SAFETY SYSTEMS
SERIAL NUMBER:		805
CALIBRATION DATE:		February 11, 2004
TEST PARAMETER	SPECIFICATION	TEST RESULTS
TEMPERATURE	19°C to 26°C	24
RELATIVE HUMIDITY	10% to 70%	18
PEAK RESULTANT ACCELERATION	225 G_z to 275 G_z	246.4
PEAK LATERAL ACCELERATION	15 G_z Maximum	6.6
IS ACCELERATION CURVE UNIMODAL?	YES	YES

HEAD ACCELEROMETER CALIBRATION INFORMATION


ID. NUMBER	MANUFACTURER	MODEL NUMBER	SERIAL NUMBER	DATE OF LAST CALIBRATION	DATE OF NEXT CALIBRATION
1 - LONGITUDINAL	ENDEVCO	7264-2000T	J38127	08/22/03	02/23/04
2 - LATERAL	ENDEVCO	7264-2000T	J37980	08/22/03	02/23/04
3 - VERTICAL	ENDEVCO	7264-2000T	J37854	08/22/03	02/23/04

REMARKS:

FMVSS 201U - Headform Calibration Drops

Max: 0.3 [g] at 0.010 [s]
Min: -211.5 [g] at 0.001 [s]

Headform X Acceleration




C40500 - February 11, 2004

FMVSS 201U - Headform Calibration Drops

Max: 0.2 [g] at 0.007 [s]
Min: -6.6 [g] at 0.001 [s]

Headform Y Acceleration




C40500 - February 11, 2004

FMVSS 201U - Headform Calibration Drops

Max: 127.1 [g] at 0.001 [s]
Min: -1.2 [g] at 0.007 [s]

Headform Z Acceleration




C40500 - February 11, 2004

FMVSS 201U - Headform Calibration Drops

Max: 246.4 [g] at 0.001 [s]
Min: 0.0 [g] at -0.042 [s]

Headform Resultant



C40500 - February 11, 2004

**PART 572L
HEAD DROP POST-TEST**

MANUFACTURER:		FIRST TECHNOLOGY SAFETY SYSTEMS
SERIAL NUMBER:		0355
CALIBRATION DATE:		February 11, 2004
TEST PARAMETER	SPECIFICATION	TEST RESULTS
TEMPERATURE	19°C to 26°C	24
RELATIVE HUMIDITY	10% to 70%	18
PEAK RESULTANT ACCELERATION	225 Gs to 275 Gs	262.5
PEAK LATERAL ACCELERATION	15 Gs Maximum	1.9
IS ACCELERATION CURVE UNIMODAL?	YES	YES

HEAD ACCELEROMETER CALIBRATION INFORMATION

ID. NUMBER	MANUFACTURER	MODEL NUMBER	SERIAL NUMBER	DATE OF LAST CALIBRATION	DATE OF NEXT CALIBRATION
1 - LONGITUDINAL	ENDEVCO	7264-2000T	J28671	08/22/03	02/23/04
2 - LATERAL	ENDEVCO	7264-2000T	J32779	08/22/03	02/23/04
3 - VERTICAL	ENDEVCO	7264-2000T	J25854	08/22/03	02/23/04


REMARKS:

FMVSS 201U - Headform Calibration Drops

Max: 3.1 [g] at 0.004 [s]

Min: -232.5 [g] at 0.001 [s]

Headform-X Acceleration




C40500 - February 11, 2004

FMVSS 201U - Headform Calibration Drops

Max: 1.5 [g] at 0.002 [s]
Min: -1.9 [g] at 0.001 [s]


Headform Y Acceleration



FMVSS 201U - Headform Calibration Drops

Max: 121.9 [g] at 0.001 [s]
Min: -1.4 [g] at 0.006 [s]

Headform Z Acceleration




C40500 - February 11, 2004

FMVSS 201U - Headform Calibration Drops

Max: 262.5 [g] at 0.001 [s]
Min: 0.0 [g] at -0.047 [s]

Headform Resultant



C40500 - February 11, 2004

**PART 572L
HEAD DROP POST-TEST**

MANUFACTURER:		FIRST TECHNOLOGY SAFETY SYSTEMS
SERIAL NUMBER:		1253
CALIBRATION DATE:		February 11, 2004
TEST PARAMETER	SPECIFICATION	TEST RESULTS
TEMPERATURE	19°C to 26°C	24
RELATIVE HUMIDITY	10% to 70%	18
PEAK RESULTANT ACCELERATION	225 Gs to 275 Gs	267.8
PEAK LATERAL ACCELERATION	15 Gs Maximum	13.8
IS ACCELERATION CURVE UNIMODAL?	YES	YES

HEAD ACCELEROMETER CALIBRATION INFORMATION


ID NUMBER	MANUFACTURER	MODEL NUMBER	SERIAL NUMBER	DATE OF LAST CALIBRATION	DATE OF NEXT CALIBRATION
1 - LONGITUDINAL	ENDEVCO	7264-2000T	J41006	08/22/03	02/23/04
2 - LATERAL	ENDEVCO	7264-2000T	J40994	08/22/03	02/23/04
3 - VERTICAL	ENDEVCO	7264-2000T	J41007	08/22/03	02/23/04

REMARKS:

FMVSS 201U - Headform Calibration Drops

Max: 9.9 [g] at 0.004 [s]
Min: -238.2 [g] at 0.002 [s]

Headform X Acceleration




C40500 - February 11, 2004

FMVSS 201U - Headform Calibration Drops

Max: 1.5 [g] at 0.004 [s]
Min: -13.8 [g] at 0.002 [s]

Headform Y Acceleration




C40500 - February 11, 2004

FMVSS 201U - Headform Calibration Drops

Max: 121.8 [g] at 0.002 [s]
Min: -0.6 [g] at 0.020 [s]

Headform Z Acceleration




C40500 - February 11, 2004

FMVSS 201U - Headform Calibration Drops

Max: 267.8 [g] at 0.002 [s]
Min: 0.0 [g] at -0.050 [s]

Headform Resultant



C40500 - February 11, 2004